


American Concrete Institute®
Advancing concrete knowledge

Means and Methods of Evaluating Reinforced Concrete Structures

ACI Fall 2012 Convention
 October 21 – 24, Toronto, ON

ACI
 WEB SESSIONS



Stephen Foster joined WJE in 2010 and since that time has investigated, evaluated, and provided rehabilitation services on numerous structural and architectural projects. His project work experience includes concrete, steel, masonry, and wood structures. Mr. Foster also prepares construction documents for various repair projects. His professional affiliations include the American Concrete Institute, International Concrete Repair Institute, National Association of Corrosion Engineers, and Structural Engineers of Texas.

ACI
 WEB SESSIONS

CONDITION ASSESSMENT AND CONCRETE REPAIR STRATEGIES AT WATER TREATMENT STRUCTURES







STEPHEN FOSTER
 WISS, JANNEY, ELSTNER ASSOCIATES, INC.



OUTLINE OF PRESENTATION

- Background
- Assessment Strategies
- Results
- Service Life Modeling
- Repair Approach
- Conclusions
- Questions



BACKGROUND INFORMATION

Task:

- Comprehensive condition assessment

Goals:



- 30 years of additional service life
- Develop scope for repair documents

BACKGROUND INFORMATION

Structure:

- In service since 1986
- 128 ft [39 m] diameter
- 5,000 psi [34.4 MPa]
- 10 years of noted distress
- Moderate amount of chlorides in H₂O

TYPICAL BEAMS

Beams:


- 220 beams
- 1ft x 8in [305 mm x 203 mm]
- "Ears" support filter media



TYPICAL GIRDER

Girders:


- 106 girders
- 18 in square [457 mm]
- 16 ft long [4.9 m]



TYPICAL PIER


Piers:

- 208 piers
- 14 in diameter [356 mm]
- 3 to 3-1/2 ft tall [0.9 to 1.1 m]



PREVIOUS REPAIRS ON TF2

- Cracked beam "ears"
- Cracking of slab
- Missing hairpin reinforcement at beams
- Beam end spalls
- Sealant joint at wall



PREVIOUS REPAIRS ON TF2

- Cracked beam "ears"
- Cracking of slab
- Missing hairpin reinforcement at beams
- Beam end spalls
- Sealant joint at wall



PREVIOUS REPAIRS ON TF2

- Cracked beam "ears"
- Cracking of slab
- Missing hairpin reinforcement at beams
- Beam end spalls
- Sealant joint at wall



PREVIOUS REPAIRS ON TF2

- Cracked beam "ears"
- Cracking of slab
- Missing hairpin reinforcement at beams
- Beam end spalls
- Sealant joint at wall




PREVIOUS REPAIRS ON TF2

- Cracked beam "ears"
- Cracking of slab
- Missing hairpin reinforcement at beams
- Beam end spalls
- Sealant joint at wall




GOALS OF ASSESSMENT



Task:

- Comprehensive condition assessment

Goals:

- 30 years of additional service life
- Develop scope for repair documents

- Develop wholesale understanding of the structure
- Focus maintenance strategies at critical locations
- Precision in repair documents
- Repair now or later?



GOALS OF ASSESSMENT

Task:

- Comprehensive condition assessment

Goals:

- 30 years of additional service life
- Develop scope for repair documents

ASSESSMENT STRATEGIES

- Tools for concrete assessment
 - Field Investigation
 - Laboratory Evaluation





ASSESSMENT STRATEGIES



- Field Investigation
 - Visual Survey/ Acoustic Sounding
 - Cover Survey
 - Half-Cell Potential
 - Corrosion Rate
 - Carbonation Testing
 - GPR




VISUAL/ACOUSTIC/COVER SURVEY

100% Visual and Acoustic Survey
Over 575 cover measurements
Avg. Cover: 1.19 in. [30 mm] to 2.06 in. [52 mm]

- Identify concrete delaminations
- Document cracking patterns
- Non-destructive cover survey – verified by core and half cell locations
- Locate Half-Cell, Corrosion Rate, & Core locations based on visual results

VISUAL/ACOUSTIC/COVER SURVEY

Likely salt hydration distress (physical sulfate attack)
Test for sulfate in soil and concrete

- Paste erosion along soil line at exterior of perimeter wall






HALF-CELL POTENTIAL

ASTM C876: Corrosion Potentials of Uncoated Reinforcing Steel in Concrete

- > -200mV = 90% probability of no corrosion
- < -350 mV 90% probability of corrosion

- Indication of corrosion risk for reinforcement
- Factors: moisture, continuity, carbonation, delaminations, adjacent soil






HALF-CELL POTENTIAL

Interpreting Results:

- Dry in AZ!
- Moisture increases from beams → girders → piers → slab
- Look for "hot" spots

- Saturated concrete = more negative potentials (less resistance)






HALF-CELL POTENTIAL

Interpreting Results:

- Dry in AZ!
- More moisture from beams → girders → piers → slab
- Look for "hot" spots

- General potential gradient = more negative at bottom of Trickingling Filter
- Look for "hot" spots






HALF-CELL POTENTIAL

Interpreting Results:

- Dry in AZ!
- Moisture increases from beams → girders → piers → slab
- Look for "hot" spots

- Uniform HCP gradient = corrosion not likely

HALF-CELL POTENTIAL

Interpreting Results:

- Dry in AZ!
- Moisture increases from beams → girders → piers → slab
- Look for "hot" spots

• "Hot" spot = possible area of corrosion

HALF-CELL POTENTIAL

ASTM C876:

- >200mV = 90% probability of no corrosion
- <-350 mV 90% probability of corrosion

• Measures potential difference between reinforcement and copper-copper sulfate electrode

Electrode	Half Cell Reaction	Volts
Au	$Au^{3+} + 3e$	+ 1.498
O_2	$O_2 + 4H^+ + 4e = 2H_2O$	+ 1.229
Pt	$Pt^{2+} + 2e$	+ 1.2
Pd	$Pd^{2+} + 2e$	+ 0.987
Ag	$Ag^+ + e$	+ 0.799
$2H_2$	$2H_2 = H_2^{2+} + 2e$	+ 0.788
Fe^{3+}	$Fe^{3+} + e$	cathodic reaction
O_2	$O_2 + 2H_2O + 4e = 4OH^-$	+ 0.401
Cu	$Cu^{2+} + 2e$	+ 0.337
Sr^{2+}	$Sr^{2+} + 2e = Sr$	- 0.15
Zn	$Zn + 2e = H_2$	0.000
Pb	$Pb^{2+} + 2e$	- 0.126
Sn	$Sn^{2+} + 2e$	- 0.136
Ni	$Ni^{2+} + 2e$	- 0.250
Co	$Co^{2+} + 2e$	- 0.277
Cd	$Cd^{2+} + 2e$	- 0.403
Fe	$Fe^{2+} + 2e$	- 0.440
Cr	$Cr^{3+} + 3e$	- 0.744
Zn	$Zn^{2+} + 2e$	- 0.763
Al	$Al^{3+} + 3e$	- 1.662
Mg	$Mg^{2+} + 2e$	- 2.363
Na	$Na^+ + e$	- 2.714
K	$K^+ + e$	- 2.925

Anodic reaction

HALF-CELL POTENTIAL

• Interpreting results

- Positive Values
 - Is concrete dry?
 - Electrical interference
 - Reversed leads
 - Poor contact to reinforcement

HALF-CELL POTENTIAL

• Interpreting results

- Carbonated concrete (more positive)

Carbonated Concrete
 R is high
 Fe²⁺-conc. is high
 Micro cells occur
 Mixed potentials

HALF-CELL POTENTIAL

• Interpreting results

- Delaminations (more positive)

Delamination

HALF-CELL POTENTIAL

• Interpreting results

- Concrete adjacent to soil (depends)


Soil

CORROSION RATE TESTING

Gecor™
 $0.1 \mu\text{A}/\text{cm}^2$= passive
 >0.1 to $0.5 \mu\text{A}/\text{cm}^2$ = low
 >0.5 to $1 \mu\text{A}/\text{cm}^2$ = moderate
 >1 $\mu\text{A}/\text{cm}^2$ = very high corrosion

Feliu et al. 1996; Andrade and Alonso 1996


- Measures instantaneous snapshot of corrosion rate by measuring polarization resistance (Stern-Geary Equation)
- Temperature and moisture will influence readings
- Beams=0.05 $\mu\text{A}/\text{cm}^2$
- Girders = Wall = 0.35 $\mu\text{A}/\text{cm}^2$



CARBONATION TESTING

Typical concrete: pH 12-14
 Passive layer of steel may deteriorate: pH 9.5-11
 Phenolphthalein: pink = pH>9
 25 yrs = ~1 in. [25 mm] typical concrete

- Carbonation progresses ~0.04 in [1 mm]/year in typical concrete
- Moisture + oxygen + low pH = corrosion




CARBONATION TESTING

Typical concrete: 25 yrs = ~1 in. [25.4mm] typical concrete
 Most rapid at R.H. 50-70%
 Carbonation depth typ. less than 1 in. [25 mm] inside of tank

- Influenced by relative humidity – CO₂ transport limited when pores are saturated
- Carbonation depth: beams < girders < piers

MEASURED CARBONATION DEPTHS, IN. [MM]

Element	Minimum	Maximum	Average
Beams	0.25 [6.4]	0.25 [6.4]	0.25 [6.4]
Girders	0.25[6.4]	0.75 [19.1]	0.53 [13.6]
Piers	0.38 [9.5]	1.00 [25.4]	0.57 [14.5]




GROUND PENETRATING RADAR

Results:
 GPR on 74 of 196 beams with hairpins, randomly selected


Vertical and horizontal scans
 All scans showed hairpins in place

- Non-destructive technique to verify presence of steel hairpins at the ends of beams



ASSESSMENT STRATEGIES

- Laboratory Evaluations
 - Petrography
 - Compressive Strength
 - Rapid Chloride Permeability (RCP)
 - Sulfate Content
 - Soil Testing
 - Chloride Content




PETROGRAPHY & COMPRESSIVE STRENGTH

ASTM C856
 Standard Practice for Petrographic Examination of Hardened Concrete

ASTM C42
 Standard Test Method for Obtaining and Testing Drilled Cores and Sawn Beams of Concrete


- Assess the general composition of concrete and identify any distress mechanism
- 0.4 to 0.5 w/c ratio
- No ASR/DEF
- Avg. strength = 6,740 psi [46.5 MPa]



RAPID CHLORIDE PERMEABILITY

ASTM C1202
Standard Test Method for Electrical Indication of Concrete's Ability to Resist Chloride Ion Penetration

- Measures resistance of concrete to chloride penetration
- Results:
 - 480 to 1015 coulombs
 - Avg = 800 coulombs = very low permeability




Charge passed, coulombs	Chloride ion penetrability
14000	High
2000 to 4000	Moderate
1000 to 2000	Low
100 to 1000	Very low
<100	Negligible

SULFATE CONTENT & SOIL TESTING

ASTM C265
Standard Test Method for Water-Extractable Sulfate in Hydrated Hydraulic Cement Mortar

ASTM C1580
Test Method for Water-Soluble Sulfate in Soil

- Concrete: 1.4% (by mass) sulfate at depth of 0 to 1 in. [25 mm] = 1.5 x background content
- Soil: 0.1% (by mass) = "moderate sulfate exposure" per ACI 318



CHLORIDE CONTENT ANALYSIS

ASTM C1152
Standard Test Method for Acid-Soluble Chloride in Mortar and Concrete

ASTM C1218
Standard Test Method for Water-Soluble Chloride in Mortar and Concrete


- Chloride content vs. depth – level of reinforcement
- Chloride corrosion threshold:
 - 0.2% by weight of cement
 - 350 ppm by weight of concrete
 - ~1 lb/cu yd of concrete
- Some chlorides bound in concrete (not available to promote corrosion)

CHLORIDE CONTENT ANALYSIS

Background chloride content = 70 ppm

Revised Chloride Threshold → 420ppm

"Hump" due to transport method: Water flow → Absorption → Diffusion




Depth (in)	MSC1 (acid)	MSC1 (water)	MSC1 difference	MTC3 (acid)	MTC3 (water)	MTC3 difference
0	70	70	0	70	70	0
0.5	400	250	150	450	200	250
1	380	240	140	420	180	240
2	250	180	70	280	120	160
3	220	150	70	220	100	120
4	180	120	60	150	80	70

CHLORIDE CONTENT ANALYSIS

Piers:
>500 ppm at reinforcement

Beams/Girders:
<400 ppm at reinforcement

Top of Wall:
500-800 ppm at reinforcement



Depth (in)	Chloride (ppm)	Beam cover	Girder cover	Pier cover
0	70	70	70	70
0.5	180	180	180	180
1	650	300	450	650
2	250	250	250	250
3	150	150	150	150

RESULTS OF ASSESSMENT

- Beams
- Girders
- Piers
- Perimeter Wall
- Slab



BEAM RESULTS

- Cracking along the beam "ears" that support the filter media
- Transverse cracking on top of beams across girder support
- Cores taken at HCP "hot spots" – no significant corrosion

Avg. Cover = 1.54 in. [39 mm]
 Carbonation = 0.25 in. [6.4 mm]
 HCP = 20% showed potential "hot spots"
 Chloride content = <400 ppm at reinforcement

GIRDER RESULTS

- Transverse cracking at ~20% of top portion of girder between beams

Avg. Cover = 1.5 in. [38 mm]
 Carbonation = 0.53 in. [13.6 mm]
 HCP = 35% showed potential "hot spots"
 No distress on sides or bottom

Depth (in.)	Chloride Content (ppm)
0	100
0.5	150
1	250
1.5	350
2	500
2.5	400
3	250
4	150
5	120
6	100

GIRDER RESULTS

- Cracking / delaminations at beam bearing at the center standpipe
- Restrained thermal contraction of beams

Avg. Cover = 1.5 in. [38 mm]
 Carbonation = 0.53 in. [13.6 mm]
 HCP = 35% showed potential "hot spots"
 No distress on sides or bottom

PIER RESULTS

- Cracking and corrosion at transverse reinf. – many repaired with epoxy previously
- Limited oxygen & saturated concrete = "black" rust, less expansive than "red" rust

Avg. Cover = 1.2 in. [30 mm]
 Avg. Carbonation = 0.57 in. [14.5 mm]
 HCP = 40% of piers showed "hot spots" along transverse reinforcement
 Chlorides = 300-500 ppm at reinforcement

PERIMETER WALL RESULTS




- Deteriorated sealant joint at slab
- Isolated delaminations at interior
- Distress / delams along top of wall
- Paste erosion / scaling along soil line

Cover : < 1 in. [25 mm] in some locations on top
 High chlorides at top of wall (400 - 800 ppm)


SLAB RESULTS

- No systemic visual/acoustic distress
- Isolated discrete surface delaminations (~1-2 sq. ft.)
- Cores taken at delaminations; no corrosion observed

Avg. Cover = 2 in. [51 mm]
 Avg. Carbonation = 0.5 in. [13 mm]
 Chloride content = 100-200 ppm at reinforcement



- ### REPAIR STRATEGIES
- Goal: 30 years of additional service life
 - Repair all observed damage
 - Focus long-term maintenance strategies at critical areas
 - Piers
 - Shortest remaining service life
 - Top of Wall
 - High chlorides
 - 50% delamination



REPAIR STRATEGIES

Focus Long-Term Maintenance at critical areas:

- Pier jackets

Alternate:

- Coating system


- Stay-in-place for with sacrificial cathodic protection system




RECOMMENDATIONS FOR WALL

Focus Long-Term Maintenance at critical areas:

- Top of wall



Coating system to prevent ingress of chlorides

RESURFACING SYSTEM AS SPECIFIED: EXTEND DOWN FACE OF WALL 4" MIN., TYP.


EXISTING CONC. TO REMAIN, TYP.

4" MIN.

1/2" MIN.



TERMINATE SYSTEM IN SAWCUT REGLET, TYP.

Repair top of wall install galvanic anodes



CONCLUSIONS

- Advantages of comprehensive condition assessment
 - Develop wholesale understanding of the structure
 - Focus maintenance strategies at critical locations
 - Creates precision in repair documents
 - Final repair quantities $\pm 10\%$ from Construction Documents

Condition Assessment and Concrete Repair Strategies

QUESTIONS?

