



QuakeCoRE
NZ Centre for Earthquake Resilience

Damage to Concrete Buildings with Precast Floors in the 2016 Kaikoura Earthquake

Rick Henry and Ken Elwood
University of Auckland
New Zealand





14 Nov 2016 Kaikoura EQ

M_w 7.8











13 separate faults

extending over ~150 km





Kaikoura EQ Response Spectra Wellington





Initial Reports in Wellington

- Significant shaking
- Non-structural damage
- Some isolated structural damage
- Lack of URM damage





Statistics House




Site classes: Semmens et al 2010

Statistics House


Double tee units collapsed from L1 and L2




Statistics House



Statistics House




Statistics House



Unit
spalling

Ledge
spalling




Further Damage

- Impacted buildings in Wellington
 - Deep soil sites (basin effects)
 - Flexible moment frame buildings 5-15 storeys (spike in spectra between 1-2s)
 - Precast floor damage (long duration → frame elongation)
- Damage discovered during detailed examinations
- Initiated Wellington City Council targeted damage evaluations





Targeted Damage Evaluations




- ✓ 64 inspected buildings with precast floors
- ✓ 8 others with significant damage

Observed damage:





Hollowcore seating details



**Pre-2000s : typ 50mm seating specified
0-50mm achieved?**

Hollowcore floor damage





1994 Northridge Earthquake



QuakeCoRE
NZ Centre for Earthquake Resilience



Matthews and Bull (2004) 2-bay x 1-bay specimen



Matthews(2004)



UoC test –
Matthews
(2004)



2.5% drift



Kaikoura EQ damage



Incompatible displacements





Matthews et al (2004)



UoC test –
Matthews
(2004)

Assessment of Precast Floors


– Demands



Elongation

- Fenwick and Megget (1993)


Unidirectional Plastic hinge



Unidirectional plastic hinge:

$$e = \theta \frac{(d - d')}{2}$$

Reversing Plastic hinge





Reversing plastic hinge:

$$e = C\theta \frac{(d - d')}{2}$$

(NZS 3101: C=2.6)


Elongation

$$e = 2.6 \frac{\theta_p}{2} (d - d') \leq 0.036 h_b$$




Rotation

- Movement at support ledge due to rotation added to elongation




**Rotation and
Elongation**



Rotation only

Wall elongation



Kaikoura EQ damage



Drift Capacity of Hollowcore Floors

– *Failure modes*

Loss of Seating
(LOS)



Positive Moment Failure
(PMF)



Negative Moment Failure
(NMF)



Objective:

- Determine inter-storey drift at which floor units no longer have reliable gravity load path.


Hollowcore Floors

– test data (*Des Bull + students*)

Name	Researcher	Date	Type	Seating (mm)	Loading	Failure mode	Drift capacity (%)
HC1-B-03	Bull and Matthews	2003	old	50	rot only	PMF	3.0
HC4-B-03	Bull and Matthews	2003	old	50	rot only	PMF	1.8
S1-L-04	Liew	2004	old	0	rot only	NMF	1.1
S2-L-04	Liew	2004	old	70	rot only	NMF	1.9
S3-L-04	Liew	2004	old-retro	20	rot only	NMF	1.8
HC1-J-07	Jensen	2007	old	35	rot+elong	LOS	1.7
HC3-J-07	Jensen	2007	old	50	rot+elong	LOS	1.7
HC4-J-07	Jensen	2007	old-retro	50	rot+elong	LOS + slide	2.5
HC2-J-07	Jensen	2007	old	75	rot+elong	Slide	-
HC2-B-03	Bull and Matthews	2003	new	70	rot only	Slide	-
HC3-B-03	Bull and Matthews	2003	new	70	rot only	Slide	-
S1-T-04	Trowsdale	2004	new	75	rot+elong	Slide	-
S1-M-05	Macpherson	2005	new	75	rot+elong	Slide	-
S2-M-05	Macpherson	2005	new	75	rot+elong	Slide	-

Loss of reliable load path

Pre-2006 details






Loss of Seating (LOS) - Spalling

- Kaikoura evidence




Loss of Seating (LOS)



Positive Moment Failure

Potential cracks




Crack at back of unit → Loss of Seating (LOS) critical

Crack in unit → Positive Moment Failure (PMF) critical




Matthews (2004)




Kaikoura EQ damage

Negative Moment Failure (NMF)



If NMF triggered
→ **Limiting drift = 1%**



Liew 2004


Be aware of:

- *Low gravity loads*
- *Strong or short starters*

Hollowcore Floors – test data

- *Validation of assessment*

Drift at Loss of Reliable Load Path



Summary

- Wellington vs. Christchurch
 - Long duration → frame elongation → floor damage
- Precast floor damage
 - Most issues with older detailing in existing (80s) buildings
 - Damage often hidden – ***How to inspect?***
 - Floors fragile – ***easily damaged, but how to repair?***
- Precast floor assessment provisions developed
 - www.eq-assess.org.nz



QuakeCoRE
NZ Centre for Earthquake Resilience

Thank you!
Questions?











ENGINEERING





Photo: Sally Dellow, GNS Science











Hollowcore



Refer to Table 5 -1 for reference numbers

7 Negative moment zone due to continuity with the support reduces the shear strength of the floor.

(a) Current practice



Examples: Beam Hinging



Plastic Hinge Damage



ENGINEERING

If ANY of the following apply, ***plastic hinge*** residual capacity may have been reduced by earthquake:

1. Total crack width in plastic hinge $> 0.005d$
2. Sliding has occurred on a crack
3. Wide ($>0.5\text{mm}$) diagonal cracks
4. Concrete degradation, indicated by significant spalling (concrete cover can be removed by hand)

If none apply:

Do not expect degradation in strength, deformation capacity, or energy dissipation; but expect degradation in stiffness leading to larger displacement demands in next event.









Critical Damage States – Primary structure



ENGINEERING

- Very critical ↑
- A: Local collapse risk (without aftershock)**
- A1 Transverse cracking at ends of hollow core or ribs within 400mm of the support beam, plus either associated vertical dislocation or diagonal crack in web
 - A2 Significant damage to support for flange-hung double tee floor units
- B: Local or global collapse risk in aftershock**
- B1 Transverse cracking at ends of hollow core floor units or ribs within 400mm of the supporting beam & not classified as A1
 - B2 Reduced precast floor unit support
 - B3 Loss of lateral support for columns over multiple stories
 - B4 Shear damage to corner columns
- Less critical ↓
- C: Damage to primary structure posing lower risk**
- C1 Plastic hinge damage
 - C2 Web cracking in hollow core floor units
 - C3 Longitudinal cracking of hollow core floor units
 - C4 Mesh fracture in floor toppings

Types of Transverse Cracks



	Transverse cracking - Visible from top	Transverse cracking - Visible from bottom	Transverse cracking - Full depth
CDS A			
CDS B		 <i>Crack within ~400mm of support</i>	
Other		 <i>Crack beyond ~400mm of support</i>	

Examples: Support Damage




Mechanisms

- Past research (Fenwick and Bull) highlighted effects of elongation and poor precast support detailing




Transverse cracks at end of hollowcore

- Ends trapped or weak section at end of starters
- No reinforcement (long or trans)
- Prestressed strand not fully developed
- Positive or negative moment failure





(b) Positive moment flexural failure with critical section near front face of support (see Section A4)



(a) Negative moment flexural failure




Examples: Transverse Cracks



Examples: Transverse Cracks





Examples: Transverse Cracks



Longitudinal Cracks in Hollowcore



Topping Cracks



ING

Repair and Retrofit





RING




Unit movement (same for all unit types)

- For rotation only case, consider unit movement due to starter bar plastic strain:




- Most units considered as restrained (i.e. use $\delta_{el}/2$)

Loss of Seating (LoS)



Negative Moment Failure (NMF)

Retrofit support:



Liew 2004

- *Effectively same as shorter starters!*

→ *Keep retrofit supports below the unit to ensure no contact!
(Stay tuned for results from ongoing research.)*