

American Concrete Institute

ACI Committee 362

Agenda

Salt Lake City, Utah

March 26, 2018

- 1.0 CALL TO ORDER AND WELCOME
- 2.0 ATTENDANCE AND INTRODUCTIONS
- 3.0 PRESENTATION
 - Premature Failure of Flange Connectors in Precast Parking Garages by Clay Naito
- 4.0 APPROVAL OF FALL 2017 MINUTES
- 5.0 STATUS OF ACI 362.2 - GUIDE FOR STRUCTURAL MAINTENANCE OF PARKING STRUCTURES
- 6.0 SUBCOMMITTEE/TASK GROUP STATUS UPDATE
 - Supplemental Cementitious Materials (Gleich/Aultmann)
 - Barrier Wall Detailing (Adams)
 - Protective Surface Treatments (Pulver)
 - Mixed Use of Coated/Uncoated Bars (Ahmed)
 - Expansion Joints – New task group
 - Snow Chutes – New task group
- 7.0 FUTURE PRESENTATIONS TO COMMITTEE
 - Potential Topics:**
 - Punching Shear Failure of Precast Ledges – Gary Klein
 - Load Distribution of Double-Tee Flanges – Harry Gleich
 - Barrier Cables - Jeff Adams
 - Protective Sealer – Brian Pulver
 - Maintenance Documents – Jim Donnelly
 - Dapped Tee Ends – Gary Klein, Blake Andrews
 - Expansion Joints - Mo Iqbal
 - Other suggestions
- 8.0 REPORT FROM PCI GARAGES COMMITTEE
- 9.0 OLD BUSINESS
- 10.0 NEW BUSINESS
 - Updating 362.1R-12 Guide for the Design and Construction of Durable Concrete Parking Structures
- 11.0 NEXT MEETING: Las Vegas, NV – Monday, October 15, 2018 – 1:00 to 5:00 pm
- 12.0 ADJOURN