

---

---

**ACI SUBCOMMITTEE 350-E MEETING AGENDA**

---

---

**TO:** J. ARDAHL (VICE-CHAIR) K. HARVEY (SECRETARY)  
S. CLOSE K. JACOBSON  
C. GENTRY S. MARQUES  
C. HANSKAT D. MCCARTHY  
D. HARGER  
  
S. SACHDEV

**CONSULTING MEMBERS:**

D. KOHL  
N. LEGATOS  
L. MRAZEK  
N. PRACHAND

**ASSOCIATE MEMBERS:**

D. ELMER  
P. GUPTA  
V. GUPTA  
L. KRAUSER

**FROM:** RAMON LUCERO

**DATE:** SUNDAY NOVEMBER 2, 2008

**LOCATION:** HOTEL: RENAISSANCE GRAND AND AMERICA'S CENTER, ST. LOUIS, MISSOURI

**TIME:** 1:00 PM – 5:00 PM

---

1. CALL TO ORDER

- a) Subcommittee Roster and Attendance
- b) Announcements
- c) Approval of Los Angeles Meeting Minutes
- d) Presentation by Mr. Steve Close and Mr. Pawan Gupta on current technological developments of unbonded tendons and their use in Environmental Concrete Structures

## 2. OLD BUSINESS

### Progress Report Task Force:

- a) Updates to Chapters 16, 18 and 19 of new ACI 350.XX based on revisions done in ACI 318-05 and ACI 318-08

Chapter 16 – Completed (Andrew Minogue)

Chapter 18 – Steve Close & Dan McCarthy

Chapter 19 – Completed (Ryan Harvey and Sal Marques)

- b) Revise (dome) minimum thickness for monolithic concrete and shotcrete, as well as for pre-cast concrete, to be consistent with Section 19.2.7. Also, clarify whether the 2 inch thickness for the outer shell of a ribbed dome only applies to un-reinforced elements – otherwise increase this thickness.

Reason: A dome roof is a shell and should meet the code requirements already defined for shells. The code should not have inconsistencies for similar elements covered in different sections. For ribbed domes, I feel that 2 inches is too thin to provide adequate corrosion protection if the section is reinforced.

Task Force: Dan McCarthy

- e) Revise required concrete cover at reinforcement in shells/domes to be consistent with Section 7.7.

Reason: A dome roof is a shell and should meet the code requirements already defined for shells. The code should not have inconsistencies for similar elements covered in different sections.

Task Force: Dan McCarthy, Ryan Harvey & Sal Marques

- f) Revise minimum cover for membrane slabs to be the same as specified for slabs on grade.

Reason: In my opinion, 1” cover is too low for slabs in EECS.

Task Force: Dan McCarthy, Ryan Harvey & Sal Marques

- g) In Appendix section G.3.1: Replace “4 in” with “5 ¾ in”. Concrete cast on earth requires a minimum of 3 in. of cover (7.7.1(a)) under the reinforcement and another 2 in. of cover (7.7.1(b)) over it.

Task Force: Dan McCarthy, Ryan Harvey & Sal Marques

- h) In Appendix section G.3.1: Replace “5 in” with “5 ¼ in”. See section 7.7.3.1

Task Force: Dan McCarthy, Ryan Harvey & Sal Marques

- i) In Appendix Section G.3.1: Replace “6 in” with “7 in”. See section 7.6.2

Task Force: Dan McCarthy, Ryan Harvey & Sal Marques

- j) Proposal by Jon Ardahl to re-visit Section 18.16.3 addressing hydrostatic pressure requirements of un-bonded single strand tendons in Environmental Concrete Structures.
- k) Development of Chapter 22 “Pre-stressed Circular Walls” (Ramon Lucero & Steve Close)

3. NEW BUSINESS

- a) Incorporation of Appendix H into the main body of the Code

4. REPORTS

- a) Prepare report for Wednesday’s session of the full 350 Committee

5. ADJOURN