

american concrete institute

ACI Committee 362

Agenda

Philadelphia, Pennsylvania

October 24, 2016

- 1.0 CALL TO ORDER AND WELCOME
- 2.0 ATTENDANCE AND INTRODUCTIONS
- 3.0 APPROVAL OF SPRING 2016 MINUTES
- 4.0 MEMBERSHIP CHANGES
- 5.0 SESSION AT FALL 2016 CONVENTION
 - Status of speaker preparation
- 6.0 UPDATING ACI 362.2 - GUIDE FOR STRUCTURAL MAINTENANCE OF PARKING STRUCTURES
 - Figures
 - Chapter 5 - Developing A Maintenance Program
 - Chapter 2 - Deterioration Associated With Parking Structures
 - Chapter 6 - Service Life And Resiliency
 - Chapter 3 - Protection Systems
 - Status of Chapters 1 and 4
 - Status of Appendix C
- 7.0 SUBCOMMITTEE/TASK GROUP STATUS UPDATE
 - Supplemental Cementitious Materials (Gleich) - Ballot
 - Barrier Wall Detailing (Adams) - TAC Request
 - Protective Surface Treatments Task Group (Walker) - Outline
 - Mixed Use of Coated/Uncoated Bars (Ahmed) - TAC Request, Membership
- 8.0 FUTURE PRESENTATIONS TO COMMITTEE
 - Load distribution in double-tee beam flanges
 - Rapid-cycle construction
 - Punching shear failure of a precast ledge
 - Diaphragms in precast garages
 - Other suggestions
- 9.0 REPORT FROM PCI GARAGES COMMITTEE
- 10.0 ACI 548.8 - TYPE EM POLYMER OVERLAY SPECIFICATION
- 11.0 OLD BUSINESS
- 12.0 NEW BUSINESS
- 13.0 NEXT MEETING: Detroit, Michigan – Monday, March 27, 2016 – 1:00 to 5:00 pm
- 14.0 ADJOURN