

# **Errata**

## **ACI CP-20(08), 1<sup>st</sup> Printing**

References to the Sample Written Examination Questions that pertain to SP-2 are incorrect on page C-10 of the Inspector Workbook. The following page is the corrected version.

## ANSWERS TO SAMPLE WRITTEN EXAMINATION QUESTIONS

Number	Correct Answer	Reference
1.	D	ACI 301, 4.2.2.3
2.	A	ACI 301, 2.2.2.1
3.	D	PCA, C. 6, pp. 105-118
4.	C	ACI 304R, Fig. 5.3(d)
5.	A	ACI 304R, 2.2.5
6.	D	ACI 305R, 2.8.2, 4.2.5, 4.3.2
7.	D	ACI 306R, 2.7
8.	C	SP-2, p. 83; PCA C. 10, p. 226
9.	B	ACI 309R, Table 7.1
10.	C	ACI 318, 1.3.4
11.	C	ACI 318, 7.8.1.4
12.	A	ACI 347, 3.7.2.3
13.	D	ASTM E329, 10.2.2, 10.2.5, 10.3
14.	A	ASTM C94, 3.2
15.	D	CRSI, C. 3, Sec. 3.6, p. 3-3
16.	D	PCA, C. 14, p. 254
17.	B	ACI 304.2R, 4.2.1
18.	A	ACI SP-2, C. 1, p. 8; C. 7, pp. 53-54
19.	A	ACI SP-2, C. 1, p. 8; C. 7, pp. 53-54
20.	A	ACI SP-2, C. 5, p. 51
21.	B	ACI SP-2, C. 5, p. 51
22.	C	ACI SP-2, C. 1, p. 9
23.	D	ACI SP-2, C. 7, p. 60-61
24.	E	ACI SP-2, C. 1, p. 10
25.	D	ACI SP-2, C. 8, p. 68
26.	A	ACI 116R, p. 72
27.	C	ACI 116R, p. 3
28.	B	ACI 301, 4.3.2.1
29.	C	ACI 302.1R, 8.3.3, 11.5; PCA C. 8, p. 144
30.	A	ACI 302.1R, 8.3.3, 8.3.10, 11.8
31.	A	ACI 304R, Fig. 2.1 a-c
32.	A	ACI 304R, 2.5
33.	B	PCA, C. 6, C. 8, pp. 107, 136
34.	B	ACI 304R, 4.5