

American Concrete Institute

ACI Committee 362

Agenda

Las Vegas, Nevada

October 15, 2018

- 1.0 CALL TO ORDER AND WELCOME
- 2.0 ATTENDANCE AND INTRODUCTIONS
- 3.0 APPROVAL OF SPRING 2018 MINUTES
- 4.0 MINI-SESSION AT QUEBEC (SPRING 2019 CONVENTION)
 - Status of Session Approval
 - Confirmation of Speakers
 - Potential Topics: Update regarding diaphragm research (Ned Cleland), Update of flange connector research (Clay Nato), Repair of flange connectors (Peter Tarara), Punching shear failure of a precast ledge (Gary Klein), Behavior of dapped tee ends (Gary Klein, Blake Andrews), other suggestions
- 5.0 TAC COMMENTS OF ACI 362.2 - GUIDE FOR STRUCTURAL MAINTENANCE OF PARKING STRUCTURES
- 6.0 SUBCOMMITTEE/TASK GROUP STATUS UPDATE
 - Supplemental Cementitious Materials (Surali)
 - Barrier Wall Detailing (Adams)
 - Protective Surface Treatments (Pulver)
 - Mixed Use of Coated/Uncoated Bars (Ahmed)
 - Expansion Joint – (Iqbal)
 - Snow Chutes
 - Repair of Cracks in Parking Garages (D’Arcy, ??)
- 7.0 FUTURE PRESENTATIONS TO COMMITTEE

Potential Topics:

 - Punching Shear Failure of a Precast Ledge – Gary Klein
 - Load Distribution of Double-Tee Flanges – Harry Gleich
 - Barrier Cables - Jeff Adams
 - Protective Sealer – Brian Pulver
 - Maintenance Document – Jim Donnelly
 - Dapped Tee Ends – Gary Klein, Blake Andrews
 - Expansion Joints - Mo Iqbal
 - Other suggestions
- 8.0 REPORT FROM PCI GARAGES COMMITTEE
- 9.0 OLD BUSINESS
 - Updating 362.1R-12 Guide for the Design and Construction of Durable Concrete Parking Structures
- 10.0 NEW BUSINESS
- 11.0 NEXT MEETING: Quebec City, Quebec - Monday, March 25, 2019 – 1:00 to 5:00 pm
- 12.0 ADJOURN